### **UNCLASSIFIED**

# AD NUMBER AD815512 **NEW LIMITATION CHANGE** TO Approved for public release, distribution unlimited **FROM** Distribution authorized to U.S. Gov't. agencies only; Administrative/Operational Use; 17 APR 1967. Other requests shall be referred to Naval Civil Engineering Labs., Port Hueneme, CA. **AUTHORITY** USNCBC ltr, 24 Oct 1974

## **し**

#### FOR OFFICIAL USE ONLY

Technical Note N-886

ROTECTION OF FLOATING PONTOONS FROM CORROSION -- PART I.

INSTALLATION AND INITIAL PERFORMANCE OF TEST FLOATS

10 by

Richard W. Drisko, Ph. D.

108

17 April 1967

#### INTERNAL WORKING PAPER

Each transmittal of this document outside the agencies of the U.S. Government must have prior approval of the U.S. Naval Civil Engineering Laboratory.

U. S. NAVAL CIVIL ENGINEERING LABORATORY Port Hueneme, California

#### FOR OFFICIAL USE ONLY

PROTECTION OF FLOATING PONTOONS FROM CORROSION -- PART I.

INSTALLATION AND INITIAL PERFORMANCE OF TEST FLOATS

Technical Note N-886

Y-F015-11-04-632A

bу

Richard W. Drisko, Ph. D.

#### ABSTRACT

A test program has been initiated that is aimed at reducing the maintenance costs associated with the recoating of deteriorated pontoon camel floats. Three 2-coat protective coating systems have been applied to pontoons on three test floats, and a material and labor cost analysis has been made on coating pontoons with each of these systems. A separate phase of the investigation is aimed at corrosion mitigation by cathodic protection. One of the test floats is currently being protected with zinc anodes, another with aluminum anodes, and the third float is serving as an unprotected control. After six months service to the fleet, the test pontoon camel floats were in good condition. No coating deterioration was noted, and the cathodic protection systems were providing electrical potentials that insure complete protection from corrosion to any exposed steel.

Each transmittal of this document outside the agencies of the U. S. Government must have prior approval of the U.S. Naval Civil Engineering Laboratory.

#### INTRODUCTION

Steel pontoons are one of the most widely used structural components in the Naval Shore Establishment. While they find many uses ashore, they are more commonly used in water to impart floatation to structures.

The Navy Public Works Center, San Diego, requested assistance from the Naval Facilities Engineering Command and the U. S. Naval Civil Engineering Laboratory in a program designed to reduce the cost of maintaining pontoon floats used as camels by ships of the fleet berthing at Navy docking facilities in San Diego Bay. This type of camel is widely used throughout the Naval Shore Establishment as a fender system to prevent abrasion damage to moored vessels. While thus serving the fleet, the protective coatings on these floats are subjected to extensive impact and abrasion damage in addition to their usual deterioration in an hostile marine environment.

#### BACKGROUND

The Navy utilizes about 450 pontoon camel floats of differing size and design in service to the fleet in San Diego Bay. They are secured to a centrally-located pier (Figure !) from which they can be readily delivered to ships desiring their use. It has been the standard practice at PWC, San Diego, to protect the steel pontoons from corrosion with a protective coating of MIL-C-18480A, a cold-applied coal tar coating. Because of the deterioration of this coating by abrasion, fouling organisms, and other environmental factors (Figure 2), it has been necessary to recoat the floats annually.

The Navy Public Works Center, San Diego, desired that the maintenance cycle for camel floats be extended to at least three years. In order to further reduce maintenance costs, they desired that the coating be applied in no more than two coats. Accordingly, three two-coat protective coating systems were selected for testing on pontoon camel floats in San Diego Bay.

Much of the damage to came! floats occurs below the water line, causing them to sink. Thus cathodic protection was also investigated in this study as a means of extending the service time of the floats before required overhaul and thus further reducing maintenance costs.

#### TEST DESIGN

Three coating systems utilizing a corrosion-inhibiting primer and a compatible topcoat were selected for use in the test program. The selections were based on performance of the coatings on mooring buoys, steel sheet piling,  $9^{-13}$  and other steel specimens 14 located in a marine environment. The three systems are described below and their sources and analyses are given in Appendices A and B, respectively.

Paint System 1 consists of one coat of epoxy-polyamide primer (Devran 201) and one epoxy-polyamide topcoat (Devran 204). In previous work  $^{1-14}$  polyamide-cured epoxies have been found to have good abrasion resistance and perform well in a marine environment.

Paint System 2 consists of one coat of an epoxy-polyamide primer (Proline 2001) and a coal tar epoxy topcoat (Proline 2002). The coal tar epoxy coating imparts good resistance to moisture penetration. Although some coal tar epoxies tend to become brittle when exposed to ultraviolet light, System 2 has performed well in San Diego Bay on a limited number of pontoon floats, as well as on the underwater portion of a test mooring buoy.

Paint System 3 consists of one coat of self-cured zinc inorganic silicate (Carbo-Zinc 11) and one coat of high-build polyamide-cured epoxy (Carboline 190 HB). Zinc inorganic silicates without a topcoating have provided good protection to steel in sea water for two or more years, and a topcoat should extend their service lives considerably. A self-cured rather than a post-cured zinc inorganic coating was used to reduce labor costs. Paint systems similar to System 3 have been used extensively to protect the atmospheric portions of off-shore drilling platforms.

Two different types of sacrificial anodes were utilized in the cathodic protection portion of the investigation. Both of these, zinc and aluminum, have previously been investigated by the Navy for other related work. In the test program, three pontoon camel floats were in-service tested. One of these floats was cathodically protected with zinc anodes, a second with aluminum anodes, and the third was not cathodically protected but served as a control.

Each test float consisted of three pontoons spaced a pontoon length apart and secured together with steel angle-iron bracing (Figure 3). They are commonly called 1x5's, because they have a width of one and a length of five pontoons. The test design for the three floats is shown in Figure 4. Each of three paint systems investigated was applied to one of the three pontoons in each test float. The pontoons in each float were arranged randomly as shown in Figure 4, so that each coating system would have the same magnitude of exposure to impact and abrasion damage. The design also permitted a study of the effect of each cathodic protection system on each of the three coating systems.

#### FABRICATION OF TEST FLOATS

The three test floats were fabricated along with other pontoon camel floats by PWC, San Diego, personnel as part of the regular work schedule. The pontoons were individually coated before the float was assembled (Figure 5). The sandblasting of the steel to white metal and the coating application were done by skilled workmen according to instructions provided by the NCEL project scientist and the coating suppliers. No difficulty was encountered in applying any of the coatings. There was some loss of the topcoat of System 1, however, because of high winds that arose during application of this coating. The thickness of each component of the three test coating systems is given in Table 1. Material and labor coats associated with coating application were determined for each coating system, so that the annual maintenance cost for coating of a pontoon camel float with each of the test coatings can be determined at the conclusion of the test.

#### COST ANALYSIS

An analysis of the costs (other than that for coating materials) for coating three pontoons is given in Table 2. It can be seen from this table that such costs totaled \$56.84, regardless of which coating system was used. The coating material costs and coverages for three pontoons are given in Table 3. The relatively high cost of the primer of System 3 is related to the high cost of its zinc pigmentation. The overall cost for coating three pontoons with each of the test coating systems is given in Table 4. It can be seen from this table that the range of costs per square foot (\$.22-.25) is so small that if one of the systems gave as little as 15% greater service life, it would be the most economical one to use.

The pontoons in the test floats have a draft of about 1½ feet (about 1/3 the height), as shown from the level of the fouling on Figure 2, and consequently require very little anode metal to protect them cathodically. Thus two small, flat sacrificial anodes were secured to each cathodically protected pontoon, one on each side near the bottom where they will be continually immersed in sea water. They were secured with nuts to steel studs welded to the pontoons for easy removal and replacement. The weights and costs of these anodes are given in Table 5. Although the initial cost of the aluminum is greater than that of zinc, its relative current output and efficiency are reported by the supplier to make aluminum competitive with zinc. In any case, a long service life at very low cost is expected from each type of anode.

#### PERFORMANCE TO DATE

The three test camel floats were placed in the storage area (Figure 6) along with other such floats available for fleet use. These floats are being used extensively by the fleet (Figure 7) receiving the type of service for which they were designed. In such use, they accumulate a film of oil at the water line from floating oil in the harbor and an accumulation of miscellaneous debris dumped over the side of the moored vessels (see Figure 7). Nevertheless, the three coating systems have provided excellent service with no apparent damage after six months of service to the fleet. The tops of the pontoons were cleaned with sea water and a stiff bristle brush before examining the coating.

The two cathodically protected floats are receiving excellent protection from their anodes. The pontoon-to-water potentials were measured with a portable field meter using a silver-silver chloride reference half-cell. The float protected by zinc anodes had a potential of-1.04 volts and the float protected by aluminum anodes had a potential of-1.00 volts. Both are well above the level of-0.85 voits considered to be necessary for complete protection. One obvious difference in the electrodes is that the zinc anodes are free of fouling while the aluminum anodes have much loose tunicate fouling on them. This has mistakenly caused workmen in the area to believe that the aluminum anodes were not functioning properly.

#### REFERENCES

- 1. U. S. Naval Civil Engineering Laboratory. Technical Report R-246: Protection of mooring buoys--Part I. Initiation of field testing, by R. W. Drisko and R. L. Alumbaugh. Port Hueneme, Calif., June 1963.
- 2. ——. Technical Report R-258: Protection of mooring buoys-Part 11. First rating inspection, by R. W. Drisko. Port Hueneme, Calif., Oct. 1963.
- 3. ——. Technical Report R-291: Protection of mooring buoys--Part III. Second rating inspection, by R. W. Drisko. Port Hueneme, Calif., Apr. 1964.
- 4. ——. Technical Report R-316: Protection of mooring buoys--Part IV. Results of third rating inspection, by R. W. Drisko. Port Hueneme, Calif., June 1964.
- 5. ——. Technical Report R-355: Protection of mooring buoys--Part V. Fourth rating inspection, by R. W. Drisko. Port Hueneme, Calif., Jan. 1965.
- 6. ——. Technical Report R-385: Protection of mooring buoys--Part VI. Results of fifth rating inspection, by R. W. Drisko. Port Hueneme, Calif., June 1965.
- 7. ——. Technical Report R-431: Protection of mooring buoys--Part VIII. Results of sixth rating inspection, by R. W. Drisko. Port Hueneme, Calif., Dec. 1965.
- 8. ——. Technical Report R-458: Protection of mooring buoys--Part VIII. Results of seventh rating inspection, by R. W. Drisko. Port Hueneme, Calif., June 1966.
- 9. ——. Technical Note N-260: Corrosion prevention and protective coatings for steel piling, by A. L. Fowler, C. V. Brouillette, and H. Hochman. Port Hueneme, Calif., March 1956.
- 10. ——. Technical Note N-309: Protective coatings for steel piling: Reports of six-month test, by R. L. Alumbaugh, C. V. Brouillette and A. L. Fowler. Port Hueneme, Calif., Sept. 1957.
- 11. ——. Technical Report R-194: Protective coatings for steel piling: Results of 30-month test, by R. L. Alumbaugh. Port Hueneme, Calif., 1962.

- 12. ——. Technical Report R-397: Protective coatings for steel piling: Correlation of results of parallel exposures at Port Hueneme, and Guam, by C. V. Brouillette and R. L. Alumbaugh. Port Hueneme, Calif., Aug. 1965.
- 13. \_\_\_\_\_. Technical Report R-490: Protective coatings for steel piling: Results of harbor exposure on ten-foot simulated piling, by R. L. Alumbaugh and C. V. Brouillette. Port Hueneme, Calif., Nov. 1966.
- 14. Technical Note N-767: Protective coatings in shallow and deep ocean environments, by C. V. Brouillette, R. W. Drisko and R. L. Alumbaugh. Port Hueneme, Calif., Aug. 1965.

Table 1. Descriptions of Coating Systems

						-	
		TAMET			Topcoat		
Number Type	əd	Proprietary Name	Thick- ness (mils)	Type	Proprietary Name	Thick- ness (mils)	Total Thickness (mils)
1 Epoxy-Pc	Epoxy-Polyamide	Devran 201	E	Epoxy-Polyamide	Devran 204	7	7
2 Epoxy-Pc	Epoxy-Polyamide	Proline 2001	7	Coal Tar Epoxy	Proline 2002	7	α
3 75-5 7						.	
C THIC THO	rganic	Line inorganie   Carbo-Zine II	m	Epoxy-Polyamide	Epoxy-Polyamide   Carboline 190 HB	9	6

Table 2. Surface Preparation and Application Costs for Three Pontoons for Each Coating System—

Laborer	Time (hours)	Hourly Rate	Cost per 3 Pontoons
Sandblaster	3	2.932/	8.79
Sandblaster Helper	3	$2.93^{2/}$	8.79
Painter	7 <u>3</u> /	$3.68\frac{2}{}$	25.76
Total	Labor Costs4/		\$43.34
Cost of 12 Tons of	Sand		13.50
Total	Costs		\$56.84

<sup>1/</sup> Each system required the same labor time.
2/ Includes additional increment for dirty work.
3/ Includes mixing and clean-up time.
4/ Labor was the same for applying tomcoats as for Labor was the same for applying topcoats as for applying primers.

Table 3. Coating Material Costs and Coverages for Three Pontoons

	Coverage (sq ft per gal)	200	120 120	150 150
	Cost (per sq ft)*	0.05 0.06 0.02 0.13	0.07 0.05 0.01 0.13	0.09 0.06 0.01 0.16
Coating Materials	Total Cost (dollars)	27.30 36.40 11.73 75.43	39.50 29.95 5.40 74.85	52.80 33.00 7.20 93.00
Coa	Amount (gal)	33	N N N	4 4 6
	Type	Primer Topcoat Thinner Total	Primer Topccat Thinner Total	Trimer Topcoat Thinner Total
	System Number	-	7	m

\* Assuming 600 sq ft total surface area for three pontoons, including hardware.

Table 4. Overall Cost in Dollars for Coating Pontoons

	Sq. Ft.		0.22	0.22	0.25
System         Material Costs         Total Cost         Cost         Cost         Cost         Per Number         Costings         Sandblasting         Sq. Ft.           Number         Coatings         Sandblasting         Sq. Ft.         Sq. Ft.	78.67				
	ing	per sq ft	75.43         0.13         13.50         0.02         25.76         0.04           74.85         0.13         13.50         0.02         25.76         0.04	0.03	
Costs	Sandblast	per 3 pontoons	17.58	17.58	1
Labor	8	per sq ft	0.04	0.04	0.04
	Coating	rer 3	25.76	25.76	
		per sq ft	0.02	0.02	0.02
1 Costs	Sand	per 3 pontoons		13.50	13.50
Materia	20	per sq ft	0.13	74.85         0.13         13.50         0.02         25.76         0.04           93.00         0.16         13.50         0.02         25.76         0.04	0.16
	Coating	per 3 pontoons	75.43	_	93.00
System	Jagimon			2	6

Table 5. Description of Anodes

Anode Material	Weight (pounds)	Cost (dollars)	Cost per Pound of Anode Metal* (dollars)
Zinc	11	3.57	.32
Aluminum	9,6	7.00	.81

\*Assuming the steel core of each anode to weigh 1.4 lbs.

#### APPENDIX A

#### Suppliers of Proprietary Coatings

Devran 201 and Devran 204:

Devoe and Raynolds Company, Inc.

2625 Durahart Street

Riverside, California 92507

Proline 2001 and Proline 2002:

Pro-Line Paint Company

2545 Main Street

San Diego, California 92113

Carbo-Zinc 11 and Carboline 190 HB:

Carboline Company

32 Hanley Industrial Court St. Louis, Missouri 63144

APPENDIX B Analyses of Test Paints

System Number	Test Paint	Weight Per Gal.	Nonvolatile (%)	Drying Time* (Min.) Set-To-Touch Dry Ha	Min.) Dry Hard	Viscosity (KU)	Pigment (%)
	Devran 201 (epoxy)	12.5	70.8	12	300	9/	49.5
-	Devran 201 (converter)	9.6	67.9			99	24.5
4	Devran 204 (epoxy)	10.9	67.2	5	1,020	74	38.6
	Devran 204 (converter)	11.5	62.8	•		89	8.94
	Proline 2001 (epoxy)	14.8	77.5	5	450	85	63.0
ſ	Proline 2001 (converter)	9.1	54.3			75	
7	Proline 2002 (epoxy)	11.3	83.0	10	480	110	47.4
	Proline 2002 (converter)	7.7	64.8			62	
	Carbo-Zinc 11 (resin)	9.1	38.8	1	8	**	23.4
3	Carboline 190 HB (comp.A)	6.3	83.6	9	480	82	51.0
	Carboline 190 HB (comp.B)	10.6	9.69			63	0.44

\*For mixed components for two component systems \*\*Too thin for determination




Figure 1. Pontoon camel floats in storage ready for use by the fleet.



Figure 2. Deteriorated pontoon camel float.




Figure 3. Completed pontoon camel float ready for service.

ċ Pontoo

	Paint System No. 2
oon No. 01: Cathodically Protected With Zinc Anodes	Paint System No. 3
oon No. 01: Cathodica	Paint System No. 1

Pontoon No. 02: Cathodically Protected With Aluminum Anodes

Charles and the Charles of the Charl	Paint	System (C)	No. 3	
	Paint	System	Z o Z	
	Paint	System	No. 2	

Pontoon No. 03: No Cathodic Protection

	Paint	System	146. 2	
	Paint Walnt	System	Zo. 4	

Paint System No. 1

Figure 4. Design of Pontoon Float Test.




Figure 5. Partially fabricated test floats. Note the anode secured to each pontoon.




Figure 6. Test pontoon floats in storage available for use by the fleet.




Figure 7. Test pontoon float serving the fleet.

UNCLASSIFIED

Security Classification

Security Classification				
(Security classification of title, body of abstract and index	NTROL DATA - R&		the overall report is classified)	
1 ORIGINATING ACTIVITY (Corporate author)			RT SECURITY CLASSIFICATION	
U. S. Naval Civil Engineering Laborat	ory	UNC	CLASSIFIED	
Port Hueneme, California		26 GROU		
3. REPORT TITLE				
Protection of Floating Pontoons From Initial Performance of Test Floats	Corcosion Pa	rt I.	Installation and	
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)	·			
June 1966 March 1967				
5. AUTHOR(3) (Leat name, first name, initial)	<del></del>			
Drisko, R. W. Ph D				
Deloko, a. a. in b				
17 April 1967	7# TOTAL NO OF P	AGE!	75. NO. OF REFS	
	18 14			
Se. CONTRACT OR GRANT NO.	_ <del> </del>			
b. PROJECT NO. Y-F015- 11-04-632A	N 000			
1 1013- 11-04-032R	N-886			
<b>c</b> .	SO. OTHER REPORT	10(5) (Any	other numbers that may be assigned	
	file report)			
d.				
10. A VAILABILITY/LIMITATION NOTICES				
Each transmittal of this document out	side the accordi	aa af <b>+</b>	ha II G G.	
must have prior approval of the U. S.	Naval Civil Fo	es ul t	ne U. S. Government	
11. SUPPLEMENTARY NOTES	<del></del>			
III SUPPLEMENTARY NOTES	12. SPONSORING MILIT	ARY ACT	VITY	
	]			
	Naval Facili	ties En	gineering Command	
13. ABSTRACT	<del></del>		<del></del>	
A test program has been initiate	d that is aimed	at red	ucing the maintenance	
costs associated with the recoating o	f deteriorated	pontoon	camel floats.	

A test program has been initiated that is aimed at reducing the maintenance costs associated with the recoating of deteriorated pontoon camel floats. Three 2-coat protective coating systems have been applied to pontoons on three test floats, and a material and labor cost analysis has been made on coating pontoons with each of these systems. A separate phase of the investigation is aimed at corrosion mitigation by cathodic protection. One of the test floats is currently being protected with zinc anodes, another with aluminum anodes, and the third float is serving as an unprotected control. After six months service to the fleet, the test pontoon camel floats were in good condition. No coating deterioration was noted, and the cathodic protection systems were providing electrical potentials that insure complete protection from corrosion to any exposed steel.

DD 15084 1473 0101-807-6800

UNCLASSIFIED

Security Classification

	LIN	LINK A		< в	LIN	KC
KEY WORDS	ROLE	wT	ROLE	WT	ROLE	w T
			<b>!</b>			
Corrosion			1		1	
Protection			i 1		l i	
Came 1s			1		1	
Floats					1 1	
Pontoons			1		!!!	
Cathodic Protection	1 1		1			
Protective Coatings			1		1	
<b>3</b>	İ		f l			
	1 1		1 1			
			<b>!</b> !			
	j j		j		1	1
			1			
	! !		1		]	Ì

#### INSTRUCTIONS

- ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of De-tense activity or other organization (corporate author) issuing
- 2a. REPORT SECURITY CLASSIFICATION: Enter the overall security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordance with appropriate security regulations.
- 2b. GROUP: Automatic downgrading is specified in DoD Directive 5200.10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as author-
- 3. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classification, show title classification in all capitals in parenthesis immediately following the title.
- 4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.
- 5. AUTHOR(S): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal author is an absolute minimum requirement.
- 6. REPORT DATE: Enter the date of the report as day, month, year, or month, year. If more man one date appears on the report, use date of publication.
- 7a. TOTAL NUMBER OF PAGES: The total page count should follow normal pagination procedures, i.e., enter the number of pages containing information.
- 76. NUMBER OF REFERENCES: Enter the total number of references cited in the report.
- 8a. CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.
- 8b, 8c, & 8d. PROJECT NUMBER: Enter the appropriate military department identification, such as project number, subproject number, system numbers, task number, etc.
- 9a. ORIGINATOR'S REPORT NUMBER(S): Enter the official report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.
- 9b. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).
- 10. AVAILABILITY/LIMITATION NOTICES: Enter any limitations on further dissemination of the report, other than those

imposed by security classification, using standard statements such as:

- (1) "Qualified requesters may obtain copies of this report from DDC."
- "Foreign announcement and dissemination of this (2) report by DDC is not authorized.
- "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
- (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through
- (5) "All distribution of this report is controlled. Qualified DDC users shall request through

If the report has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if known.

- 11. SUPPLEMENTARY NOTES: Use for additional explana-
- 12. SPONSORING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address
- 13. ABSTRACT: Enter an abstract giving a brief and factual summary of the document indicative of the report, even though it may also appear elsewhere in the body of the technical re-port. If additional space is required, a continuation sheet shall he attached.

It is highly desirable that the abstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (TS), (S), (C), (C), (C), (C)

There is no limitation on the length of the abstract. However, the suggested length is from 150 to 225 words.

14. KEY WORDS: Key words are technically meaningful terms 14. KEY WORDS: Key words are technically meaningful terms or short phrases that characterize a report and may be used as index entries for cataloging the report. Key words must be selected so that no necurity classification is required. Identifiers, such as equipment model designation, trade name, military project code name, geographic location, may be used as key words but will be followed by an indication of technical context. The assignment of links, roles, and weights is optional.

UNCLASSIFIED

Security Classification

END\_7\_1967